because NIS elements, and higher echeloss with their immediate supporting statis. Not to be disseminated to consultants, external projects of

Colow-FoloBok-WolledoL

25X1

. **2** .

	el used Yugorski Strait both en route to and return from than Kara Strait which is an alternate route. A Soviet	2
	a channel through Ingoraki Strait for vessel	2
maketan thronoids this	making the passage. Vessel's serew was divinged a strait but not seriously enough to interrupt voyage.	· _
	position twice daily along the Boute to Bikson and Barents	25
	on reaching position off Osbustino, designator B, vessel	
	is compulsory in navigating the Tenisey River. Two pilot	
	a back that displayed the international pilot flag anchor	
	hmarino. One of the pilots was an experienced pilot on the was an apprentice. The former knew the river well and	8
	ce. He did not consult charts in navigating, only referre	đ
	ards which were kept in an inside pocket when not being	25
	Upon reaching position labeled designator D, just off	
	ber at subject port, a hurbor pilet boarded 1316307 and	25X
	to her burth. On departure, harbor pilot and river pilot	
	at her borth 271200F, vessel departed harber and dropped ignator D, then proceeded downstream and discharged river	
	ytanski, labeled designator C.	
		25)
Anchorage	vessel anchored in Tenisey River at designator D, where	201
	ly boards vessels. Four merchant vessels may anchor to	
load cargo from lig ever good holding g	hters at designators E, F, G and E. These anchorages are	
ALGE ROSE NOTHINE E	## 488454	25X
Marbor Marbor lavo	ut as shown on the IIS chart is accurate	
Five lumbe	r loading berths are available alongside a wooden wharf	05
	ch together with the anchorage permit loading of nine mer-	25X
chant vessels at on	e time. Depth of water alongside wharf is at least 25	ا2!
ad assission a semilar	vessel was drawing 21' when fully loaded and had plo	bea.
or water. A lighter located at designat	r berth is located at designator J. The dock wifice is	
CONTRACTOR OF THE WASHINGTON	AND AND	
Tenisey River cutsi for one hour. The	s bearded by a party of four officials at anchorage in de barber at 1312007. The boarding party remained aboard customs officer scaled vessel*s radio and all cameras. ar, sextant, provisions, binoculars, flares, or personal	
effects. Vessel di	d not have guns or ammunition on board. Seamen's papers	25
	seel was given a "superficial" search	-
	I was boarded by the same party 271100F. Papers were check	ked.
	searched. After having a lunch of sandviches and beer boarding officials and agent departed 271200F. During	
	call, one armed sentry was posted at vessel's ganguay on	
wharf. This sentry	checked identification papers of all persons boarding and	
	her armed sentries were seen patrolling wharf and barbor	
	permitted ashore were the vessel's master and first	
GLILCUT ING MASTER	r was the only one of these two persons to actually go only to the dock office to sign the bill of lading cover-	
	The master went ashere to take care of this business with-	
	ind. The vessel's chief engineer was permitted by special	
arrengement to go a	share in the company of an armed female sentry to have his	
	ked by a female dector is a small dispensary located in a	
email building on the	he dock. To other crew numbers were permitted ashore.	25)
Marbo: Craft	several river boats towing lighters loaded with	
lumber: Crare	அமை மன்ற கூறை இது இது முக்கு இது இது இது இது இது இது இது இது இது இத	2
		- ئـــــ
	sel moored 1317557 at berth labeled designator K alongside	
woogen weart. Come	encing 132000F, vessel leaded 2250 standards lumber. Carg tixuous, and loading was completed 270600F. Lumber was	
promit deciete by	truck transport and was loaded aboard vessel by ship's	
	ations for all five vessels berthed alongside lumber load-	
	the supervision of a cargo augerintendent. He was a well	
	I who saw to it that the lumber was properly loaded. He	
	C-O-N-F-I-D-N-N-I-I-A-L NO DISSUM ADROAD LIMITED	
MOFORIE		

Approved For Release 2008/07/25 : CIA-RDP80-00926A008400710001-5

C-O-N-F-I-D-K-N-T-I-A-L

25X1

st subject port.	lies of any type were	berth was at least 25° available, and no bunkers can be suppli	.64
Cargo was offlow while vessel was	set port. A after departing subject ded from vecsel at Igas analoged wif repair y	minor ship repairs may be freighter went aground off t port with a full cargo of lumber. rka and a diver inspected hull damage and located at designator L. Ten days the were paid for by the Soviet govern-	
Merciant Yessels port	3 67 00	ral merchant vessels present at subject	
Seaplane at designator Q.		ne was moored alongside a scaplane base	
Attitude of Loca	l People	attitude of Soviet nationals who	25
boarded vessel v time he visited enjoyed a lunch	ras much relaxed compare a Soviet port. The box of sandwiches and beer	ed with the attitude shown the last arding officials and agent sat down and before vessel sailed on the day of	
departure. The	port authorities	in-	2
		hat they would be pleased to do every- and make his visit pleasant. Whistles	
thing possible twere blown in the		•	
thing possible twere blown in the hardor on 27 Aug /Comment required to take	; 55.	It is noted that vessel was not by passage of the Northern Sea Route.	2 L 2
were blown in the harbor on 27 Aug Comment required to take the items of the items	s a pilet at Mormonsk folice field encountered es	or passage of the Morthern Sea Route. ast of Tugorski Strait, vessel seage. Subject port appeared to be in order to equal or surpass the record	. 2

Approved For Release 2008/07/25 : CIA-RDP80-00926A008400710001-5



Approved For Release 2008/07/25 : CIA-RDP80-00926A008400710001-5 E G (•D) PORT FACILITIES AT IGARKA, U.S.S.R. D_M

Approved For Release 2008/07/25 : CIA-RDP80-00926A008400710001-5



